Inventory Labels - Formats & Standards

Laboratory equipment labels are used for permanent identification of fixed assets or as information labels. Destructible labels cannot be entirely peeled off and applied to another spot. Labels are resistant to high and low temperatures, humidity, chemical solvents, oil and UV. White matte label surface provides good barcode reading.

| SHAPE | SIZE (mm) | MATERIAL | APPLICATION | SOLUTION | SYMBOL |
|-------|-----------|-----------------|-------------|-----------|----------|
| | 50 x 30 | P4-11300 series | MANUAL | EQUIPMENT | P4-11301 |



















